#### **ENVIRONMENTAL CHEMISTS**

#### Analysis For Total Metals By EPA Method 200.8

Client ID: M05442 Client: Alaskan Copper Works
Date Received: 03/25/10 Project: Metro Self Monitor, F&BI 003248

Date Extracted: 03/26/10 Lab ID: 003248-01 x10
Date Analyzed: 03/29/10 Data File: 003248-01 x10.067

Matrix: Water Instrument: ICPMS1 Units: ug/L (ppb) Operator: AP

Lower Upper Internal Standard: % Recovery: Limit: Limit: Germanium 88 60 125

17.3

Concentration ug/L (ppb)

Chromium 551
Nickel 425
Copper 478

Zinc

#### **ENVIRONMENTAL CHEMISTS**

## Analysis For Total Metals By EPA Method 200.8

Client ID: Method Blank
Date Received: Not Applicable
Date Extracted: 03/26/10

Date Extracted: 03/26/10
Date Analyzed: 03/29/10
Matrix: Water
Units: ug/L (ppb)

Client: Alaskan Copper Works
Project: Metro Self Monitor, F&BI 003248

Lab ID: I0-161 mb
Data File: I0-161 mb.044
Instrument: ICPMS1

Operator: AP

Lower Upper Internal Standard: % Recovery: Limit: Limit: Germanium 97 60 125

Concentration
ug/L (ppb)

Chromium <1
Nickel <1
Copper <1
Zinc <1

#### **ENVIRONMENTAL CHEMISTS**

Date of Report: 04/01/10 Date Received: 03/25/10

Project: Metro Self Monitor, PO M05542, F&BI 003248

## QUALITY ASSURANCE RESULTS FOR THE ANALYSIS OF WATER SAMPLES FOR TOTAL METALS USING EPA METHOD 200.8

Laboratory Code: 003246-01 (Duplicate)

_Analyte	Reporting Units	Sample Result	Duplicate Result	Relative Percent Difference	Acceptance Criteria		
Chromium	ug/L (ppb)	<1	<1	nm	0-20		
Nickel	ug/L (ppb)	<1	<1	nm	0-20		
Copper	ug/L (ppb)	21.7	21.7	0	0-20		
Zinc	ug/L (ppb)	81.7	82.9	1	0-20		

Laboratory Code: 003246-01 (Matrix Spike)

		Spike	Sample	Percent Recovery	Acceptance
Analyte	Reporting Units	Level	Result	MS	Criteria
Chromium	ug/L (ppb)	20	<1	106	67-132
Nickel	ug/L (ppb)	20	<1	101	73-119
Copper	ug/L (ppb)	20	21.7	102 b	50-144
Zinc	ug/L (ppb)	50	81.7	95 b	46-148

Laboratory Code: Laboratory Control Sample

	Analyte	Reporting Units	Spike Level	Percen Recover LCS		Acceptance Criteria				
	Chromium	ug/L (ppb)	20	108	66-135					
	Nickel	ug/L (ppb)	20	108	67-134					
i	Copper	ug/L (ppb)	20	105	66-134					
	Zinc	ug/L (ppb)	50	101	<b>57-1</b> 35	3.13				

#### **ENVIRONMENTAL CHEMISTS**

## **Data Qualifiers & Definitions**

- a The analyte was detected at a level less than five times the reporting limit. The RPD results may not provide reliable information on the variability of the analysis.
- A1 More than one compound of similar molecule structure was identified with equal probability.
- b The analyte was spiked at a level that was less than five times that present in the sample. Matrix spike recoveries may not be meaningful.
- ca The calibration results for this range fell outside of acceptance criteria. The value reported is an estimate.
- c The presence of the analyte indicated may be due to carryover from previous sample injections.
- d The sample was diluted. Detection limits may be raised due to dilution.
- ds The sample was diluted. Detection limits are raised due to dilution and surrogate recoveries may not be meaningful.
- dv Insufficient sample was available to achieve normal reporting limits and limits are raised accordingly.
- fb Analyte present in the blank and the sample.
- fc The compound is a common laboratory and field contaminant.
- hr The sample and duplicate were reextracted and reanalyzed. RPD results were still outside of control limits. The variability is attributed to sample inhomogeneity.
- ht Analysis performed outside the method or client-specified holding time requirement.
- ip Recovery fell outside of normal control limits. Compounds in the sample matrix interfered with the quantitation of the analyte.
- j The result is below normal reporting limits. The value reported is an estimate.
- J The internal standard associated with the analyte is out of control limits. The reported concentration is an estimate.
- jl The analyte result in the laboratory control sample is out of control limits. The reported concentration should be considered an estimate.
- jr The rpd result in laboratory control sample associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- is The surrogate associated with the analyte is out of control limits. The reported concentration should be considered an estimate.
- lc The presence of the compound indicated is likely due to laboratory contamination.
- L The reported concentration was generated from a library search.
- nm The analyte was not detected in one or more of the duplicate analyses. Therefore, calculation of the RPD is not applicable.
- pc The sample was received in a container not approved by the method. The value reported should be considered an estimate.
- pr The sample was received with incorrect preservation. The value reported should be considered an estimate.
- ve Estimated concentration calculated for an analyte response above the valid instrument calibration range. A dilution is required to obtain an accurate quantification of the analyte.
- vo The value reported fell outside the control limits established for this analyte.
- x The sample chromatographic pattern does not resemble the fuel standard used for quantitation.

003248			S.A.	MPLE CHA	in of C	ust	OD	Y	^	16	<del>-</del>	03/	25	110	7		AI
		0-1		SAMPLEAS/	signature)				•				-				
Send Report To Genzus THOMPSON				DDO IFOT NA	ME/NO	_	1,000	_	$\geq$		DC	١. #	- 1	□ Sta		NAROUNI	
Company ALASKAN CORPER Works			PROJECT NAME/NO. PO # Mestro Self monden M65442							1 2	☐ Standard (2 Weeks)						
Address 628	S. HANG	et so	_	11100100	2010-	M	M4	w		<i>"</i> (	Ω2	445		Rush	chai	rges autho	rized by:
City, State, ZIP_See	THE WA	9813	34	REMARKS	7			15						⊓ Die		APLE DIS	
Phone # 266-571-60														□ Ret	urn :	samples	•
Phone #_200341 60	<u>/30_</u> Fax # <u><i>CE</i></u>	6-002-4	307					-						□ Wil	call	with inst	ructions
									_ {	ANA	LYS	ES REC	QUEST	ΓED			
	-					    -	ine	21B	092	SVOCs by 8270		NES				(B) (6)	
Sample ID	Lab ID	Date	Time	Sample Type	# of containers	Dies	asol	8	\$ 8	á	E			1			Notes
	160				containers	TPH-Diesel	TPH-Gasoline	BTEX by 8021B	VOCs by 8260	ပ္လို	-	3		1		<b>2</b> ()	
							П	BI	۶	S		B					
m05442	01	3/25/10	1:00	tho	/							X					
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1							$\exists$		T				$\top$			1	
									$\exists$			1	T				
,	,							7	1	7	7	7	1				·
	n 1		-			H	7	7	$\dashv$	_		+	+		-		
						H		+		-	$\dashv$	+	+-	1	_	0	
- 1 <del>1/2-1/2011-2011-2011-2011-2011-2011-2011</del>							+	+	$\dashv$		-	+	+	+	_	+	<del></del>
						$\vdash$	$\dashv$	$\dashv$	+	_	$\dashv$		+	┢	-	+-	
				-		$\vdash$	$\dashv$	$\dashv$	+	+	+	+	+	-	-	┼	
Friedman & Bruya, Inc.		SIGNATUI	) F	L	PRINT	NAN	(F)			_		COM	DANIV	_	_ _	DATE	TIME
3012 16th Avenue West		SIGNATOR		, 7		1						1	FAIT		-76		1:447
Seattle, WA 98119-	Received by:	/ -	Genzer Thompson						FEBI			1	- -	3/25/10 3/26/10	1.88 /2		
Ph. (206) 285-8282	Relinquished by	and	Whan Phan			- 5		-				porto	-				
Fax (206) 283-5044	Received by:											-	-		+		
FORMS\COC\COC.DOC				1					75	4						, (	) (
												Sar	nples	rec	eive	d at $18$	°C

#### **ENVIRONMENTAL CHEMISTS**

James E. Bruya, Ph.D. Charlene Morrow, M.S. Yelena Aravkina, M.S. Bradley T. Benson, B.S. Kurt Johnson, B.S. 3012 16th Avenue West Seattle, WA 98119-2029 TEL: (206) 285-8282 FAX: (206) 283-5044 e-mail: fbi@isomedia.com

April 1, 2010

Gerry Thompson, Project Manager Alaskan Copper Works 628 South Hanford Seattle, WA 98134

Dear Mr. Thompson:

Included are the results from the testing of material submitted on March 25, 2010 from the Metro Self Monitor, PO M05542, F&BI 003248 project. There are 4 pages included in this report. Any samples that may remain are currently scheduled for disposal in 30 days. If you would like us to return your samples or arrange for long term storage at our offices, please contact us as soon as possible.

We appreciate this opportunity to be of service to you and hope you will call if you have any questions.

Sincerely,

FRIEDMAN & BRUYA, INC.

Kortland Orr Project Manager

Enclosures ACU0401R.DOC